

MiNi 3D 3 Axis Gimbal For Aircraft

Firmware V1.13 Update Explanation

Firmware Update explanation

V1.13 2015.7.3

1. Optimized the performance of the pitching rotation when controlling by remote control.
You can choose the firmware of **Rocker position mode** or **Rocker speed mode** to update.

V1.12 2015.6.9

1. Optimized the performance of the heading following.

